





Measure the current consumption of any connected USB devices and display the consumption in volts and amps.

- USB powermeter measures the power consumption in volts and amps
- 4 digit display
- Measurable voltage: 3-8 volts
- Measurable voltage: 0-3 amps
- Measuring tolerance: 1 %
- Measure the current consumption of any connected USB devices

Measure the current consumption of any connected USB devices and display the consumption in volts and amps. So you always have an overview of the actual usage of any connected USB device. This hepls you to better calculate the battery life of mobile computers.

Art. Nr. 112937



more pictures:





voltmeter (V)



consumption (A)



Art. Nr. 112937